

Fig. 3




Fig. 1




Fig. 2




Fig. 4

NOTES:

↑ - INDICATES AIR FLOW
TOP AN FRONT WIRE GUARDS AND
LAMPS WERE REMOVED FOR
CLARITY




Fig. 5




Fig. 6A




Fig. 6B




FIG. 7